



# **Journal Bearing Upgrade to Solve Reliability Issues in an Accessory Gearbox.**

**John K. Whalen, PE**  
**TCE/Turbo Components & Engineering**

**Lorenzo Aburto**  
**Conoco Phillips Alaska**


# INTRODUCTION

- Accessory gearbox on gas turbine - generator
- Gas turbine vital for operation of Alpine field on the north slope of Alaska
- Accessory gearbox journal bearings failed on several occasions – brought gas turbine down
- Failures attributed to varying load directions
- Redesigned to replace sleeve bearings with tilting pad journal bearings

# ConocoPhillips Alpine Field

- Operator: ConocoPhillips
- Located 40 miles west of Kuparuk.
- Alpine is the largest onshore oil field discovered in North America in the past 20 years.
- It began producing in late 2000.
- Its 2008 net crude oil production was 44MBD.

# ConocoPhillips Alpine Field




Map from ConocoPhillips website


# Gearbox

- Motor drives gearbox to start the gas turbine
- Also driven off the gearbox:
  - Hydraulic pump
  - Oil pump
  - Fuel pump – not used
- Once started the motor disengages and the turbine drives the pumps
- Changing from driving to driven changes bearing load directions


# Gearbox



# Gearbox




# Gearbox







# Gearbox



# Gearbox-Turbine Side



# Failed Bearings



# Failed Bearings



**#4 Journal Bearing- As installed**



# Failed Bearings



**#4 Journal Bearing- Looking at Upper Half**

# Failed Bearings



**#4 Thrust Bearing- As Installed**

# Failed Bearings



**#4 Thrust Bearing- Looking at Upper Half**


# Load Analysis

- Had center distances, speeds, and ratios
- Estimated pressure and helix angles
- Estimated hp
  - For pumps used aux motor sizes
  - Used motor HP for startup
- Two scenarios
  - Start up – driven by motor
  - Running – driven by turbine




# Bearing Numbering


**TOP VIEW**




**SIDE VIEW**



# Load Analysis – Bearing 6




LOAD AT START-UP




RUNNING LOAD

# Load Analysis – Bearing 5





LOAD AT START-UP



RUNNING LOAD



# Load Analysis – Bearing 3



# Failed Bearings



- Bearings from shaft 4 and 5 failed
- Shaft 4 experiences severe load angle changes
- Shaft 5 not as severe
- Decided to upgrade to Tilting Pad Journal Bearings
  - Reduce sensitivity to load angles
- Installed and running successfully

# Tilting Pad Journal Bearings – Bearing 3



SECTION "A-A"


# Tilting Pad Journal Bearings – Bearing 4



SECTION "A-A"





# Tilting Pad Journal Bearings – Bearing 5





# Tilting Pad Journal Bearings – Bearing 6



# CONCLUSIONS

- Changing from a driver to a driven caused bearing load angle changes
- Tilting Pad journal bearings are not as sensitive to these load angle changes
- Bored out the case to accept the larger TPJ's
- Installed and running successfully for a few years now – several starts
- ConocoPhillips has plans to upgrade spare box